

LIST OF REFERENCE STANDARDS

SR.NO	THERMAL SECTION
1	Infrared Thermometer
2	Humidity Chamber
3	Universal Calibrator
4	Digital Temp Indicator with RTD Sensor
5	Digital Temp Indicator with K Type Thermocouple
6	Dry Block Temperature calibrator
7	Digital Thermometer
8	Digital Hygro Thermometer
9	Digital Thermo Hygrometer (Temp -50 °C To 70 °C/0.1°C, Humidity 10% To 99%/1%)
10	Data Logger With Sensor
11	Digital Temperature Indicator With Sensor
12	S-Type Thermocouple With Universal Calibrator
13	Muffle Furnace